PF 10 6/82 P1	681		NRO ENTORY	National Park Service Pacific Northwest Region Cultural Resources Division			Vestin Bu 1001 Sixt Seattle, W	1920 on 98121	
2 NAME(S) OF STRUCTURE	(CARD 1 of 2)	5. ORIGINAL USE	7. CLASS	IFICATION					2 RATING
	(CARD I Ot 2)							- - -	10. DATE
St. Andrews Patrol Ca	bin	Patrol C	abin						_}
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE			,			1922	
		1							
St. Andrews Creek Wes	tside Road N-104	· Same	e. UTM	ONE EASTING		NORTHING	<u> </u>		11, REGION
4 CITY/VICINITY	COUNTY	STATE	SCALE	1:24	1.62.5	<u> </u>	QUAD		X::-
Nisqually Entrance	Pierce	Washington		OTHER -			NAME		
NPS/Mount Rainier Nat					-				
log frame, one-story, log post and beam fro wood slab chinking; swalls; l x 10 plank of Prior to 1920, there W. Toll reported the Trail. Toll's system O.A. Tomlinson's admit The Superintendent's three patrol cabins of	one-room (and lof nt porch; stove pi addle notch corner eiling sheathing; were very few shel need for backcount evolved into the nistration (1923-4 annual report for on the west side of	t), rectangular c pe on gable ridge ing with quarter 1.5" x 5.5" tongu ters for backcoun ry shelters to be construction of b 1). fiscal year 1922 the park at Mowi	abin; steeply; whole log p split ends; we and groove try rangers a placed ten to oth patrol ca reported the ch Lake, St.	-pitched cecurlins with ertical boar wood floor; and hikers. o fifteen making and traceonstruction Andrews Cree	dar shake whittled rd front concrete In 1919- iles apar ail shelt n by the ek, and a	ends; door; pier a 20, Sup t along ers und Nation t Suns	whole varnish and log perinte g the W der Sup al Park et Park	log wa ed int found ndent londerl erinte Servi	Ils with erior ation. Roger and ndent ce of cabins
were used as temporar design, with their st porches, were incorpo	eeply pitched ceda	r shaked gable ro	ofs, saddle r	otch comer:	ing, and	s log posts	frame, and bea	rectan m fram	gular e front
14 CONDITION EXCELLENT	[3 600b □	FAIR DETERIORAT	ED PUINS	15. DANGER (SPECIFY	OF DEMOLITION?	YES	Пио	∑ ⊓NKI	NOWN

S SIGNIFICANCE

St. Andrews Patrol Cabin is one of the oldest backcountry ranger stations in the park. It was intended as a temporary headquarters for rangers on patrol of the park's western boundary and the Wonderland Trail. Aspects of the cabin's log frame, rectangular design, with its steeply pitched cedar shake gable roof, saddle notch cornering, and post and beam frame front porch, were incorporated into the construction of later patrol cabins in the park. This cabin was an early component of Superintendent Roger Toll's vision of a string of backcountry shelters to accommodate backcountry patrols, and provide shelter for the hiking public; a policy that evolved and expanded under Superintendent Tomlinson's administration.

21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building File N-104, Maintenance Division, Mount Rainier National Park, building data and sketch plan, 1962.

Erwin N. Thompson, Mount Rainier National Park, Washington: Historic Resource Study, (Denver: Historic Preservation Branch, Denver Service Center, National Park Service, 1981).

22. INVENTORIED BY	AFFILIATION	DATE		
David Harvey	MORA Cultural Resources Survey	9/29/82		


PM 0 6/82	T INVENT		ational Park Service acific Northwest Region ultural Resources Divisi	n 2	Westin Building, P 1920 2001 Sixth Aven. Seattle, Washington 98121			
1. Stre I.D. NO	<u> </u>			<u> </u>	eattle, w	85111	191011 98121	
2 NAME(S) OF STRUCTURE	5 ORIGINAL USE	7, CLASSIFICA	TION			-	3. HATING	
(CARD 2 of 2)							10, DATE	
St. Andrews Patrol Cabin	Patrol Cabin							
3 SITE ADDRESS (STREET & NO)	6, PRESENT USE	<u> </u>					1922	
,	· ·				<u></u>			
St. Andrews Creek Westside Road N-104	Same	8. UTM ZONE EASTING NO			DATHING		11, REGION	
·		1						
Nisqually Entrance Pierce	Washington	SCALE	1:24 1 62.5 OTHER:		QUAD			
12 OWNER/ADMIN ADDRESS	wastangeon	1	Official		17,000			
NPS/Mount Rainier National Park, Tahoma	a Woods-Star Route, Ashf	ord, Washi	ngton					
St. Andrews Patrol Cabin, located on the front facade with roughly hewn who located in Klapar backcountry rangers on patrol in Klapar	he Westside Road on St. f 279 square feet. The le log columns and rough been reconditioned. It	Andrews Cr open porch board dec is present	eek two miles from is 5' x 16', extocking. The deck in the su	ending s eleva mmers a	the enated of	ntir Ef t	e width of he ground	
14 CONDITION DEXCELLENT GOOD	FAIR DETERIONATED	PUINS	15. DANGER OF DEMOLITION? (SPECIFY THREAT)	YE\$	Пио		Junknown	

16. SIGNIFICANCE

17 PHOTOS AND SKETCH MAP OF LOCATION

18 LOCATED IN AN HISTORIC DISTRICT?





PUBLIC ACCESSIBILITY	YES, LIMITED	UNKNOWN	TED		20. EXIŜTING SURVEYS	COUNTY	NHL HA	BS HAER-1	RBAH	□NPS	STATE
REFERENCES-HISTORIC	AL REFERENCES, PERSO	NAL CONTACTS.	AND/OR OTHER					·		•	
			•								
			•		•						
-											
, INVENTORIED BY				Ī	AFFILIATION				DATE		
									<u> </u>		